Calvert Arms Apartments: (Multiple Units)

Results by Area

NSPIRE: Annual

Scheduled: 10/10/2024 Closed: Oct 10 2024 ID: 560374

Score: 53.8

Scoring Summary - NSPIRE

Units Inspected: 15	Outside		Inside		l	Init	Totals		
HUD Samp. Size: 11	#	Pts	#	Pts	#	Pts (Adj)	#	Pts	
Life Threatening	0	0.00	0	0.00	5	20.00	5	20.00	
Severe	0	0.00	0	0.00	8	7.89	8	7.89	
Moderate	1	0.41	2	0.91	40	14.67	43	15.99	
Low	2	0.36	1	0.20	11	1.76	14	2.32	
Totals	3	0.77	3	1.11	64	44.32	70	46.20	

Score	53.8*	Note: The unit points are adjusted based on the count of units inspected and not the HUD-
		defined unit sample size. Outside and Inside points are based on the HUD Sample Size.

Message	Non-scoring findings excluded from score: (Smoke Detectors), Temporary non-scoring findings
	excluded from score, Repeated HUD Standard findings within an area are counted only once

Inspection Results

			Outside								
1 Location	Item	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By	
Main Entry	Light Fixtures (Exterior)	A permanently installed light fixture is inoperable	Exterior light inop @ primary entry door; U	nit 4 ¹	10/10/24 11:47 JM		Mod	0.413		30D	
Main Entry	Light Fixtures (Exterior)	A permanently installed light fixture is inoperable	Inop outside primary entry to Unit 7	2	10/10/24 12:02 JM		Mod	0.413		30D	
		1 Out	tside NSPIRE To	tals							
Life Threate	ening: 0/0	Severe: 0/0	Mod	erate: 2	2/0.82			Low: 0/0			
3 Location	Item	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By	
Side of Building	Site Drainage	Drainage is blocked, and water is unable to drain properly	Exterior of Unit 18	<u>3</u>	10/10/24 13:43 JM		Low	0.18	•	60D	
Side of Building	Site Drainage	Erosion is present, and the footer is exposed.	Exterior of Unit 18	<u>4</u>	10/10/24 13:44 JM		Low	0.18		60D	
		3 Out	tside NSPIRE To	tals		•			•	•	
Life Threate	ening: 0/0	Severe: 0/0	Moderate: 0/0					Low: 2/0.36			

			Inside							
Office / Clubho	use		morao							
Location	Item	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Community Room	Cooking Appliance (BLDG)	A Stove Burner is Inoperable (with at least one operable burner)	Front right burner missing	<u>5</u>	10/10/24 15:17 JM		Mod	0.45		30D
Restrooms	Sink	Sink stopper damaged, inoperable, or missing with evidence of prior installation	Stopper missing men's room sink	<u>6</u>	10/10/24 15:21 JM		Low	0.20		60D
Restrooms	Toilet (BLDG)	Toilet is damaged or inoperable (common area)	no flush	<u>7</u>	10/10/24 15:20 JM		Mod	0.45		30D
Life Threateni	ng: 0/0	Office / Clubh Severe: 0/0	nouse Inside NSF Mode	PIRE T erate: 2					Low: 1/0.2	!
			Unit							
1: Unit 01										
Location	Item	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts	Fix By
(YK Note: Occup	oied as of 7/10/20	024 USR)							(Adj)	
Bathroom 1	Sink	Sink stopper damaged, inoperable, or missing with evidence of prior installation		<u>8</u>	10/10/24 10:49 JM		Low	0.22	0.16	60D
Bathroom 1	Toilet	Toilet is not secured at base/loose	Toilet detachment @ base	<u>10</u>	10/10/24 10:44 JM		Mod	0.50	0.37	30D
Bathroom 1	Toilet	Toilet components are damaged but overall functional	Extensive water leakage observed @ base of toilet.	<u>9</u>	10/10/24 10:47 JM		Low	0.22	0.16	60D
Life Threateni	ng: 0/0	1: Unit (Severe: 0/0	01 Unit NSPIRE T Mode	otals erate: 1	/0.37			L	ow: 2/0.3	2
1: Unit 02										
Location	Item nt as of 7/10/202	Results 4 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Entire Unit	No Issues/Violations	Not Inspected - Key Does Not Work	•		10/10/24 15:52		•	0.00¹	0.00¹	
Life Threateni	ng: 0/0	1: Unit (Severe: 0/0)2 Unit NSPIRE T Mo	otals derate:	0/0				Low: 0/0	
1: Unit 03										
Location	Item pied as of 7/10/2	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
(TR Note: Occup	pied as 01 7/10/2				40/40/04				()	
Bathroom 1	Toilet	Toilet components are damaged but overall functional	@ base	<u>11</u>	10/10/24 11:02 JM		Low	0.22	0.16	60D
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	More than 12" from ceiling	<u>12</u>	10/10/24 11:00 JM		LT	0.001	0.001	24H
Closet/Storage Area	Water Heater	Pressure relief valve discharge piping is missing		<u>13</u>	10/10/24 11:03 JM		Mod	0.50	0.37	30D
Kitchen	Conductors, Outlets, Switches	Improperly wired or grounded outlet	Right side outlet has hot / neutral reversed @ kitchen countertop	14	10/10/24 11:09 JM		Severe	1.35	0.99	24H
			3 Unit NSPIRE T							
Life Threateni	ng: 1/0	Severe: 1/0.99	Mode	erate: 1	/0.37			L	ow: 1/0.10	6
1: Unit 04 Location (YK Note: Occur	Item pied as of 7/10/2	Results 024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Bathroom 1	Infestation	Evidence of cockroaches (Live,	Roaches observed in	15	10/10/24		Mod	0.50	0.37	30D
		Dead, or Other Evidence) Sink stopper damaged,	bathroom Missing @ bathroom	<u>15</u>	11:21 JM 10/10/24					
Bathroom 1	Sink	inoperable, or missing with evidence of prior installation	sink	16	11:20 JM		Low	0.22	0.16	60D
Bedroom 1	Door - General	A passage door component is damaged/missing/inoperable	Bedroom door lock will not secure	<u>17</u>	10/10/24 11:24 JM		Low	0.22	0.16	60D

Non-Scoring 2Temporary Non-Scoring 3Repeat finding within the area (only 1-scored) *Note: Unit points adjusted to reflect the actual unit count



Location I (YK Note: Occupi	Item ied as of 7/10/20	Results	Notes							
		024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Bedroom wall	<u>18</u>	10/10/24 11:23 JM		LT	0.00¹	0.00¹	24H
Hallways & Corridors S	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Behind hutch outside of bathroom door	<u>19</u>	10/10/24 11:22 JM		LT	0.00¹	0.00¹	24H
Kitchen F	Refrigerator	Refrigerator door seal is damaged	Refrigerator door seal damaged @ bottom	<u>20</u>	10/10/24 11:17 JM		Mod	0.50	0.37	30D
Main Entry [Door – Fire Labeled	Fire-labeled door seal or gasket is damaged or missing		21	10/10/24 11:12 JM		Severe	0.002	0.002	24H
	2/2		4 Unit NSPIRE To		/o ==				2/2.22	
Life Threatening	g: 2/0	Severe: 1/0	Mode	rate: 2	/0.73			Lo	w: 2/0.32	2
1: Unit 05 Location I (YK Note: Occupi	Item ied as of 7/10/20	Results 024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Bedroom 1	<u>22</u>	10/10/24 11:42 JM		LT	0.00¹	0.00¹	24H
Closet/Storage Area	Flammables or Combustibles	Combustible/Flammables material is on or within 3 feet of a fuel burning Water Heater	Flammable materials stored on top of water heater	<u>23</u>	10/10/24 11:41 JM		LT	5.45	4.00	24H
Closet/Storage Area V	Water Heater	Pressure relief valve discharge piping is missing	Piping missing; bathroom closet	24	10/10/24 11:42 JM		Mod	0.50	0.37	30D
Hallways & Corridors S	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Outside of bathroom	<u>25</u>	10/10/24 11:42 JM		LT	0.00¹	0.00¹	24H
Kitchen	Ceiling Covering and Finishes	Ceiling has signs of structural failure (cracking, small circles, blisters, or nail pops)	Kitchen ceiling; with 1 inch penetrating hole	<u>26</u>	10/10/24 11:42 JM		Mod	0.50 ³	0.373	30D
LIVING ROOM	Ceiling Covering and Finishes	Ceiling has signs of structural failure (cracking, small circles, blisters, or nail pops)	Living room ceiling has surface deterioration and suspected water damage.	<u>27</u>	10/10/24 11:42 JM		Mod	0.50³	0.373	30D
Life Three dealer	0/4		5 Unit NSPIRE To		V4 4				0/0	
Life Threatening	g: 3/4	Severe: 0/0	Mode	erate: 3	3/1.1			<u> </u>	_ow: 0/0	
1: Unit 06 Location I (YK Note: Occupie	Item ed as of 7/10/20	Results 24 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Bathroom 1 E	Bathtub/Shower	Bath/Shower component is damaged, missing, or inoperable not limiting personal hygiene	Tub faucet loose / detached	<u>28</u>	10/10/24 11:54 JM		Low	0.22	0.16	60D
Bathroom 1	Toilet	Toilet is not secured at base/loose	Toilet not secure to floor	<u>30</u>	10/10/24 11:52 JM		Mod	0.50	0.37	30D
Bathroom 1	Toilet	Toilet is damaged or inoperable (only toilet in unit)	Toilet inoperable	<u>29</u>	10/10/24 11:54 JM		Severe	1.35	0.99	24H
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling		<u>31</u>	10/10/24 11:56 JM		LT	0.00¹	0.00¹	24H
Hallways & Corridors S	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Hall outside bedroom	<u>32</u>	10/10/24 11:57 JM		LT	0.00¹	0.00¹	24H
Life Threatering	a: 2/0	1: Unit 0	06 Unit NSPIRE To					1 -	1/0 4 <i>0</i>	
Life Threatening	y. 2/0	Severe: 1/0.99	IVIOGE	rate: 1	10.31			LC	ow: 1/0.16	,
	Item ed as of 7/10/20	Results 124 USR - this tenant was	Notes relocated in Oct d	Pic ue to	Date water/m	Fixed old dam	Sev lage)	Pts	Pts (Adj)	Fix By
Alternate Location - M See Notes for Details S	Mold-Like Substances	Elevated moisture level in a unit	Throughout entire unit	33	10/10/24 12:17 JM		Mod	0.50	0.37	30D
	Bathtub/Shower	Bath/Shower component is damaged, missing, or inoperable not limiting personal hygiene	Tub faucet leaking	<u>34</u>	10/10/24 12:15 JM		Low	0.22	0.16	60D

1: Unit 07 (Cont	inued)									
Location	Item	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts	Fix By
(YK Note: Occup	oied as of 7/10/2	024 USR - this tenant was	relocated in Oct	due to	water/m	old dan	nage)		(Adj)	
Bathroom 1	Door – General	A passage door component is damaged/missing/inoperable	Bathroom door will not close	<u>35</u>	10/10/24 12:19 JM		Low	0.223	0.16³	60D
Bathroom 1	Mold-Like Substances	Moisture damage on a surface from 4 Sq. In. to 1 S.F.(Units)	Bathroom next to toilet	<u>37</u>	10/10/24 12:13 JM		Mod	0.50	0.37	30D
Bathroom 1	Mold-Like Substances	Moisture damage on a surface from 1 to 9 S.F. (Units)	Bathroom wall between toilet and tub	<u>36</u>	10/10/24 12:16 JM		Severe	1.35³	0.993	24H
Bathroom 1	Toilet	Toilet is damaged or inoperable (only toilet in unit)	Toilet inop	<u>38</u>	10/10/24 12:12 JM		Severe	1.35	0.99	24H
Bedroom 1	Door – General	A passage door component is damaged/missing/inoperable	Door lock inop @ bedroom 1	<u>39</u>	10/10/24 12:05 JM		Low	0.223	0.16 ³	60D
Bedroom 1	Floor Covering and Finishes	General Comment	Bedroom flooded with water from bathroom toilet; carpet & flooring soaked	<u>40</u>	10/10/24 12:09 JM			0.001	0.001	
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	More than 12" from ceiling, bedroom	<u>41</u>	10/10/24 12:11 JM		LT	0.001	0.001	24H
Closet/Storage Area	Water Heater	Pressure relief valve discharge piping is missing	Piping missing	<u>42</u>	10/10/24 12:18 JM		Mod	0.50	0.37	30D
Hallways & Corridors	Mold-Like Substances	Moisture damage on a surface from 1 to 9 S.F. (Units)	Mold like substance observed outside bedroom 1; above baseboard	<u>43</u>	10/10/24 12:20 JM		Severe	1.35³	0.99³	24H
Hallways & Corridors	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Detector more than 12" from ceiling; between bedroom and bathroom	<u>44</u>	10/10/24 12:10 JM		LT	0.00¹	0.00¹	24H
Life Threatening	ng. 2/0	Severe: 3/2.96	Mod	lerate: 3	3/1.1			L	.ow: 3/0.48	8
1: Unit 08 Location	Item	Results	Notes Mod	Pic	B/1.1 Date	Fixed	Sev	Pts	ow: 3/0.48 Pts (Adj)	Fix By
1: Unit 08 Location		Results 024 USR) Wall-mounted smoke alarm			Date	Fixed	Sev		Pts	
1: Unit 08 Location (YK Note: Occup	Item ied as of 7/10/20	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm	Notes	Pic	Date 10/10/24 12:33 JM 10/10/24	Fixed		Pts	Pts (Adj)	Fix By
1: Unit 08 Location (YK Note: Occup Bedroom 1 Bedroom 2	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light	Notes Bedroom 1 Bedroom 2 Lamp outside of	Pic 45	Date 10/10/24 12:33 JM	Fixed	LT	Pts 0.001	Pts (Adj)	Fix By
1: Unit 08 Location (YK Note: Occup Bedroom 1 Bedroom 2 Hallways & Corridors	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior)	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling	Notes Bedroom 1 Bedroom 2	Pic 45 46	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24	Fixed	LT LT	0.00 ¹	Pts (Adj) 0.001 0.001	24H
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior)	Results 924 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1	Pic 45 46 47	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24	Fixed	LT LT Mod	0.001 0.001 0.50	Pts (Adj) 0.001 0.001 0.37	24H 24H 30D
1: Unit 08 Location (YK Note: Occup	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door	Pic 45 46 47 48	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24	Fixed	LT LT Mod LT	0.00¹ 0.00¹ 0.50 0.00¹	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹	24H 24H 30D 24H
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @	45 46 47 48 49	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM	Fixed	LT LT Mod LT	0.00¹ 0.00¹ 0.50 0.00¹ 0.50	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37	24H 24H 30D 24H 30D
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry Main Entry	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door – Fire Labeled	Results 24 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry 8 Unit NSPIRE T	45 46 47 48 49 51 50	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM	Fixed	LT LT Mod LT Mod Mod	0.00¹ 0.00¹ 0.50 0.50 0.50	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37 0.00²	24H 24H 30D 24H 30D 30D
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door – Fire Labeled	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry 8 Unit NSPIRE T	45 46 47 48 49 51	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM	Fixed	LT LT Mod LT Mod Mod	0.00¹ 0.00¹ 0.50 0.50 0.50	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37	24H 24H 30D 24H 30D 30D
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry Life Threatenin	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door – Fire Labeled	Results 24 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry 8 Unit NSPIRE T	45 46 47 48 49 51 50	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM	Fixed	LT LT Mod LT Mod Mod	0.00¹ 0.00¹ 0.50 0.50 0.50	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37 0.00²	24H 24H 30D 24H 30D 24H 30D 24H
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry Life Threatenin 1: Unit 17 Location	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door – Fire Labeled Ing: 3/0 Item	Results 24 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing 1: Unit (Severe: 1/0 Results	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry 8 Unit NSPIRE T	45 46 47 48 49 51 50	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM	Fixed	LT LT Mod LT Mod Mod	0.00¹ 0.00¹ 0.50 0.50 0.50	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37 0.00² Low: 0/0	24H 24H 30D 24H 30D 30D
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry Life Threatenin 1: Unit 17 Location	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door - Fire Labeled ng: 3/0	Results 24 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing 1: Unit (Severe: 1/0 Results	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry D8 Unit NSPIRE T	45 46 47 48 49 51 50 Totals	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM		LT LT Mod LT Mod Severe	0.00¹ 0.00¹ 0.50 0.00¹ 0.50 0.00²	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37 0.00² Low: 0/0	24H 24H 30D 24H 30D 24H 30D 24H
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry Life Threatenin 1: Unit 17 Location	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door – Fire Labeled Ing: 3/0 Item	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing 1: Unit (Results 124 USR) Wall has a loose or detached surface covering	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry D8 Unit NSPIRE T	45 46 47 48 49 51 50 Totals	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM		LT LT Mod LT Mod Severe	0.00¹ 0.00¹ 0.50 0.00¹ 0.50 0.00²	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37 0.00² Low: 0/0	24H 24H 30D 24H 30D 24H 30D 24H
1: Unit 08 Location (YK Note: Occup) Bedroom 1 Bedroom 2 Hallways & Corridors Hallways & Corridors Kitchen Main Entry Life Threatenin 3: Unit 17 Location (YK Note: Occup)	Item ied as of 7/10/20 Smoke Alarms Smoke Alarms Light Fixtures (Interior) Smoke Alarms Cooking Appliance Door Surface - Entry (non-fire) Door - Fire Labeled Item Died as of 7/10/20 Wall Covering and	Results 124 USR) Wall-mounted smoke alarm more than 12in. from a ceiling Wall-mounted smoke alarm more than 12in. from a ceiling A permanently installed light fixture is inoperable Wall-mounted smoke alarm more than 12in. from a ceiling A Stove Burner is Inoperable (with at least one operable burner) Gap of 1/4" around door seal/gasket & light penetration Fire-labeled door seal or gasket is damaged or missing 1: Unit (Results 124 USR) Wall has a loose or detached	Notes Bedroom 1 Bedroom 2 Lamp outside of bedroom 2 inop Between bedrooms 1 and 2 Front right burner inop Light showing @ bottom of door sweep Primary entry D8 Unit NSPIRE T Mod Notes Edge of surround	45 46 47 48 49 51 50 Totals lerate: 3	10/10/24 12:33 JM 10/10/24 12:36 JM 10/10/24 12:34 JM 10/10/24 12:34 JM 10/10/24 12:30 JM 10/10/24 12:28 JM 10/10/24 12:25 JM		LT LT Mod LT Mod Severe	0.00¹ 0.00¹ 0.50 0.50 0.50 0.50 Pts	Pts (Adj) 0.00¹ 0.00¹ 0.37 0.00¹ 0.37 0.00² Low: 0/0 Pts (Adj)	24H 24H 30D 24H 30D 24H Fix By

		inspection r	resuits (d	501	Illill	ieu <i>)</i>				
3: Unit 17 (Cont	inued)									
Location (YK Note: Occu	Item upied as of 7/10/2	Results 2024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Hallways & Corridors	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	No 12" between bathroom and bedroom	<u>55</u>	10/10/24 13:06 JM		LT	0.00¹	0.00¹	24H
Kitchen	Infestation	Evidence of cockroaches (Live, Dead, or Other Evidence)	Roaches observed at pantry	<u>56</u>	10/10/24 13:00 JM		Mod	0.50	0.37	30D
Kitchen	Refrigerator	Refrigerator door handle is damaged	Handle missing on top portion of refrigerator	<u>57</u>	10/10/24 12:59 JM		Mod	0.50	0.37	30D
Kitchen	Wall Covering and Finish – Interior	Wall has a loose or detached surface covering	Kitchen; above range	<u>58</u>	10/10/24 12:58 JM		Mod	0.50 ³	0.373	30D
Living Room	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Living room	<u>59</u>	10/10/24 12:56 JM		LT	5.45	4.00	24H
Main Entry	Door – Fire Labeled	Fire-labeled door seal or gasket is damaged or missing	Primary entry	60	10/10/24 12:53 JM		Severe	0.002	0.002	24H
l ifa Thraatani	ag. 2/4		17 Unit NSPIRE To		/4 02				L ave: 0/0	
Life Threatenii	19. 3/4	Severe: 1/0	Mode	rate: 5	/1.03		;		Low: 0/0	
3: Unit 18 Location (YK Note: Occup	Item Died as of 7/10/20	Results 024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Alternate Location - See Notes for Details	HVAC Equipment	Air conditioning system is not operational	No heating or AC	61	10/10/24 13:37 JM		Mod	0.50	0.37	30D
Bathroom 1	Infestation	Evidence of cockroaches (Live, Dead, or Other Evidence)	Roaches observed; bathroom	<u>62</u>	10/10/24 13:33 JM		Mod	0.50	0.37	30D
Bathroom 1	Toilet	Toilet is damaged or inoperable (only toilet in unit)	No flush	<u>63</u>	10/10/24 13:37 JM		Severe	1.35	0.99	24H
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Bedroom 1	<u>64</u>	10/10/24 13:28 JM		LT	0.001	0.001	24H
Bedroom 1	Wall Covering and Finish – Interior	Interior wall has hole greater than 2in.	Behind door, below panel box	<u>65</u>	10/10/24 13:28 JM		Mod	0.50	0.37	30D
Closet/Storage Area	Water Heater	Pressure relief valve discharge piping is missing	Piping missing	<u>66</u>	10/10/24 13:31 JM		Mod	0.50	0.37	30D
Hallways & Corridors	Light Fixtures (Interior)	A permanently installed light fixture is inoperable	Between bedroom and bathroom	<u>67</u>	10/10/24 13:30 JM		Mod	0.50	0.37	30D
Hallways & Corridors	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	At hutch between bedroom and bathroom	<u>68</u>	10/10/24 13:26 JM		LT	0.00¹	0.001	24H
Kitchen	Conductors, Outlets, Switches	Gap of 1/2"+ in any high- voltage electrical apparatus	End of kitchen counter	<u>69</u>	10/10/24 13:22 JM		LT	5.45	4.00	24H
Kitchen	Cooking Appliance	A Stove Burner is Inoperable (with at least one operable burner)	Right front burner inop	<u>70</u>	10/10/24 13:24 JM		Mod	0.50	0.37	30D
Kitchen	Refrigerator	Refrigerator door seal is damaged	Bottom portion of door seal damaged	<u>71</u>	10/10/24 13:25 JM		Mod	0.50	0.37	30D
Kitchen	Tripping Hazard	Tripping hazard - 2in. horizontal separation	Transition strip from living room to kitchen	<u>72</u>	10/10/24 13:19 JM		Mod	0.50	0.37	30D
Living Room	Ceiling Covering and Finishes	Ceiling has signs of structural failure (cracking, small circles, blisters, or nail pops)	Kitchen and living room ceiling, water stains	<u>73</u>	10/10/24 13:16 JM		Mod	0.50	0.37	30D
Living Room	Wall Covering and Finish – Interior	Interior wall component(s) is not functionally adequate	Trim missing at left side of entry door	<u>74</u>	10/10/24 13:12 JM		Mod	0.50	0.37	30D
Life Threateni	ng: 3/4	3: Unit 1 Severe: 1/0.99	18 Unit NSPIRE To Moder		0/3.67				Low: 0/0	
3: Unit 19 Location	Item	Results	Notes	Pic	Date	Fixed	Sev	Pts	Pts	Fix By
	oied as of 7/10/20			0			50,		(Adj)	. IX Dy
Bathroom 1	Sink	Sink stopper damaged, inoperable, or missing with evidence of prior installation	Stopper missing	<u>75</u>	10/10/24 13:51 JM		Low	0.22	0.16	60D



¹Non-Scoring ²Temporary Non-Scoring ³Repeat finding within the area (only 1-scored) *Note: Unit points adjusted to reflect the actual unit count

3: Unit 19 (Cont	inued)									
Location (YK Note: Occup	Item pied as of 7/10/20	Results)24 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Closet/Storage Area	Flammables or Combustibles	Combustible/Flammables material is on or within 3 feet of a fuel burning Water Heater	Improperly stored materials on top of water heater	<u>77</u>	10/10/24 13:53 JM	•	LT	5.45	4.00	24H
Closet/Storage Area	Water Heater	Pressure relief valve discharge piping is missing	No piping observed	<u>78</u>	10/10/24 13:52 JM		Mod	0.50	0.37	30D
Hallways & Corridors	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Between bedroom and bathroom	79	10/10/24 13:50 JM		LT	0.00 ¹	0.00 ¹	24H
Kitchen	Refrigerator	Refrigerator door handle is damaged	Missing	<u>80</u>	10/10/24 13:54 JM		Mod	0.50	0.37	30D
Living Room	Ceiling Covering and Finishes	Ceiling has sagging or dropping materials	Peeling at living room ceiling	<u>81</u>	10/10/24 13:47 JM		Severe	1.35	0.99	24H
Living Room	Infestation	Evidence of cockroaches (Live, Dead, or Other Evidence)	Roaches observed, living room	<u>82</u>	10/10/24 13:48 JM		Mod	0.50	0.37	30D

3: Unit 19 Unit NSPIRE Totals

Life Threatening: 3/4 Severe: 1/0.99 Moderate: 3/1.1 Low: 1/0.16

Life Tiffeateriii	1g. 0/ +	Severe. 1/0.99	Mode	rate.	<i>)</i> / 1. 1				W. 1/0.10	
3: Unit 20 Location (YK Note: Vacar	Item nt as of 7/10/202	Results 4 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Bathroom 1	Cabinets/Vanity	General Comment	Extensive water damage and wood rot at bathroom cabinet near toilet	83	10/10/24 14:13 JM			0.001	0.00¹	
Bathroom 1	Ceiling Covering and Finishes	Ceiling has signs of structural failure (cracking, small circles, blisters, or nail pops)	Surface peeling / deterioration above toilet	<u>84</u>	10/10/24 14:15 JM		Mod	0.50	0.37	30D
Bathroom 1	Wall Covering and Finish – Interior	Interior wall has hole greater than 2in.	Behind bathroom door	<u>85</u>	10/10/24 14:11 JM		Mod	0.50	0.37	30D
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Bedroom 1	<u>86</u>	10/10/24 14:16 JM		LT	0.00¹	0.00¹	24H
Closet/Storage Area	Water Heater	Pressure relief valve terminates higher than 6in. or less than 2in. from the waste receptor flood level	Higher than 6"	<u>87</u>	10/10/24 14:10 JM		Mod	0.50	0.37	30D
Hallways & Corridors	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Between bedroom and bathroom	<u>88</u>	10/10/24 14:08 JM		LT	5.45 ³	4.00 ³	24H
Hallways & Corridors	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Switch plate cover missing; between bedroom and bathroom	<u>89</u>	10/10/24 14:09 JM		LT	5.45³	4.00³	24H
Hallways & Corridors	Smoke Alarms	Smoke alarm not installed outside a sleeping room	Between bathroom and bedroom	<u>90</u>	10/10/24 14:16 JM		LT	0.00¹	0.00¹	24H
Kitchen	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Outlet cover missing; near pantry	<u>91</u>	10/10/24 14:07 JM		LT	5.45 ³	4.00 ³	24H
Kitchen	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	No switch plate cover observed; kitchen near pantry	<u>92</u>	10/10/24 14:08 JM		LT	5.45 ³	4.003	24H
Kitchen	Infestation	Evidence of cockroaches (Live, Dead, or Other Evidence)	Kitchen sink	<u>93</u>	10/10/24 14:05 JM		Mod	0.50	0.37	30D
iving Room	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Switch plate missing at entry	94	10/10/24 14:00 JM		LT	5.45 ³	4.00 ³	24H
iving Room	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Outlet near front entry; missing cover plate	<u>95</u>	10/10/24 14:01 JM		LT	5.45 ³	4.00³	24H
iving Room	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Outlet no cover plate	<u>96</u>	10/10/24 14:02 JM		LT	5.45 ³	4.00 ³	24H
iving Room	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	Outlet no cover plate; near kitchen	<u>97</u>	10/10/24 14:03 JM		LT	5.45 ³	4.00 ³	24H
iving Room	Conductors, Outlets, Switches	Electrical conductor is not properly insulated/enclosed	No outlet cover plate; next to closet	<u>98</u>	10/10/24 14:04 JM		LT	5.45 ³	4.00 ³	24H
Main Entry	Door – Fire Labeled	Fire-labeled door seal or gasket is damaged or missing	Primary entry	<u>99</u>	10/10/24 13:59 JM		Severe	0.002	0.002	24H
Life Threatening	g: 11/36	3: Unit 2 Severe: 1/0	O Unit NSPIRE To Mode	otals rate: 4	/1.47				_ow: 0/0	





3: Unit 21 Location (YK Note: Vacan	Item t as of 7/10/2024	Results 4 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Alternate Location - See Notes for Details	Infestation	Evidence of bedbugs in 2+ Locations (Extensive)	Bedbugs throughout unit	100	10/10/24 14:20 JM		Severe	1.35	0.99	24H
			21 Unit NSPIRE To							
Life Threatenir	ng: 0/0	Severe: 1/0.99	Mod	derate:	0/0				Low: 0/0	
3: Unit 22										
Location (YK Note: Occup	Item pied as of 7/10/2	Results 2024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Alternate Location - See Notes for Details	Infestation	Evidence of bedbugs	Throughout unit	<u>101</u>	10/10/24 14:37 JM		Mod	0.50	0.37	30D
Bathroom 1	Wall Covering and Finish – Interior	Interior wall has hole greater than 2in.	Bathroom; outside of water heater closet	<u>102</u>	10/10/24 14:31 JM		Mod	0.50 ³	0.37³	30D
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Bedroom 1	<u>103</u>	10/10/24 14:28 JM		LT	0.001	0.001	24H
Bedroom 1	Wall Covering and Finish – Interior	Interior wall has hole greater than 2in.	Near bedroom door	<u>104</u>	10/10/24 14:28 JM		Mod	0.50 ³	0.373	30D
Closet/Storage Area	Door – General	Closet door component is missing, damaged or inoperable	Storage closet at primary entry door; extensive damage to frame; will not open	<u>105</u>	10/10/24 14:25 JM		Low	0.22	0.16	60D
Closet/Storage Area	Water Heater	Pressure relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material	Pipes upward	<u>106</u>	10/10/24 14:32 JM		Severe	1.35	0.99	24H
Hallways & Corridors	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Between bedroom and bathroom	<u>107</u>	10/10/24 14:29 JM		LT	0.001	0.00¹	24H
Hallways & Corridors	Wall Covering and Finish – Interior	Interior wall has hole greater than 2in.	Next to primary entry door	<u>108</u>	10/10/24 14:23 JM		Mod	0.50^{3}	0.373	30D
Living Room	Wall Covering and Finish – Interior	Wall has a loose or detached surface covering	Living entry to bathroom	<u>109</u>	10/10/24 14:35 JM		Mod	0.50	0.37	30D
Main Entry	Door – Fire Labeled	Fire-labeled door seal or gasket is damaged or missing	main entry	<u>110</u>	10/10/24 14:21 JM		Severe	0.002	0.002	24H
Life Threetenin	ag. 2/0		22 Unit NSPIRE To		/4 02				.ow: 1/0.16	
Life Threatenir	ig. 2/0	Severe: 2/0.99	Wode	rate: 5	/1.03				.OW: 1/U.16)
3: Unit 23 Location (YK Note: Occu	Item pied as of 7/10/2	Results 2024 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Bathroom 1	Sink	Sink stopper damaged, inoperable, or missing with evidence of prior installation	Stopper missing	111	10/10/24 14:45 JM		Low	0.22	0.16	60D
Bedroom 1	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Bedroom 1	<u>112</u>	10/10/24 14:40 JM		LT	0.00¹	0.00¹	24H
Closet/Storage Area	Water Heater	Pressure relief valve discharge piping is missing	Piping missing	113	10/10/24 14:46 JM		Mod	0.50	0.37	30D
Hallways & Corridors	Smoke Alarms	Smoke alarm does not produce an audio or visual alarm when tested	Between bedroom and bathroom	<u>114</u>	10/10/24 14:41 JM		LT	0.00¹	0.00¹	24H
Hallways & Corridors	Smoke Alarms	Wall-mounted smoke alarm more than 12in. from a ceiling	Between bedroom and bathroom	<u>115</u>	10/10/24 14:42 JM		LT	0.001	0.001	24H
Kitchen	Refrigerator	Refrigerator door handle is damaged	Missing; top portion of refrigerator	<u>116</u>	10/10/24 14:47 JM		Mod	0.50	0.37	30D
Living Room	Ceiling Covering and Finishes	Ceiling has a hole 2in. or more in diameter	Living room	<u>117</u>	10/10/24 14:39 JM		Mod	0.50	0.37	30D
			23 Unit NSPIRE To							

3: Unit 24 Location (YK Note: Occ	Item cupied as of 7/10/20	Results 24 USR)	Notes	Pic	Date	Fixed	Sev	Pts	Pts (Adj)	Fix By
Entire Unit	No Issues/Violations	Not Inspected - Key Does Not Work			10/10/24 19:55			0.00¹	0.00¹	
•		3: Unit	24 Unit NSPIRE	Totals						
Life Threat	tening: 0/0	Severe: 0/0	N	/loderate:	0/0			L	_ow: 0/0	