| | 1 | | | | | | |
|-----------------|-------------|-----------|---------------------|-------------------------------------|-------|---|----------------|
| Area | Bldg | Unit | Inspectable Item | Deficiency | Level | Note | date corrected |
| | Ţ. | | | | | | |
| | | | | | | still visible at bldgs:701, 2101 , 2101A, 2103 , 2104, 2107 | |
| Site | | | Grounds | Erosion/Rutting Areas | L3 | (near unit 1106), 2108, 705, 2112, 2117 and unit 1106 | incomplete |
| Building | | | | | | at mailbox kiosk: electric outlet open-uncovered | |
| Systems Systems | Bldg 2100 | | Electrical System | Missing Breakers/Fuses | L3 | exposing electric connection. | incomplete |
| Unit | Bldg 2101 | unit 1129 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | pop-up assembly | incomplete |
| Unit | Bldg 2101 | unit 1129 | Kitchen | Cabinets - Missing/Damaged | L2 | bottom kitchen cabinets not finished/painted | incomplete |
| Common | | | | | | | |
| Areas | Bldg 2103 | Floors | Patio/Porch/Balcony | Rot/Deteriorated Subfloor | L3 | unit 2122 patio slab cracked/broken/unstable | incomplete |
| Unit | Bldg 2103 | Unit 2122 | HVAC System | Not Operable | L3 | missing/inoperable | incomplete |
| | | | | Mold/Mildew/Water Stains/Water | | | |
| Unit | Bldg 2104 | Unit 1042 | Ceiling | Damage | L3 | over wasking machine | incomplete |
| | | | | | | NIS: wall patch not textured or painted near washing | |
| | | | | | | machine & sheetrock repair needed at Primary bedroom | |
| Unit | Bldg 2104 | Unit 1042 | Walls | Damaged | L2 | window | incomplete |
| | Bldg 2112- | | | | | | |
| Unit | TH | Unit 1052 | Lighting | Missing/Inoperable Fixture | L2 | kitchen light inoperable | incomplete |
| | | | | Deteriorated/Missing Seals (Entry | | | |
| Unit | Bldg 700-TH | Unit 1079 | Doors | Only) | L3 | daylight visible when entry door is closed | incomplete |
| Building | | | | | | | |
| Exterior | Bldg 701 | | Roofs | Damaged Soffits/Fascia/Soffit Vents | L2 | soffit deterioration visible | incomplete |
| Unit | Bldg 701 | Unit 2008 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | pop up assembly inoperable | incomplete |
| | | | | Mold/Mildew/Water Stains/Water | | | |
| Unit | Bldg 701 | Unit 2008 | Ceiling | Damage | L1 | bathroom at a/c air handler | incomplete |
| | | | | Damaged | | | |
| Unit | Bldg 701 | Unit 2008 | Doors | Frames/Threshold/Lintels/Trim | L3 | main entry and bathroom door frames damaged | incomplete |
| | | | | Emergency Fire Exits - | | | |
| | | | | Emergency/Fire Exits | | | |
| Unit | Bldg 701 | Unit 2008 | Health & Safety | Blocked/Unusable | L3 | bedroom window blocked | incomplete |
| Unit | Bldg 701 | Unit 2008 | Health & Safety | Hazards - Other | L3 | X2 smoke detectors-missing/removed by resident | incomplete |
| Unit | Bldg 701 | Unit 2008 | Kitchen | Sink - Damaged/Missing | L1 | kitchen faucet loose | incomplete |
| | | | | Emergency Fire Exits - | | | |
| | | | | Emergency/Fire Exits | | | |
| Unit | Bldg 705 | Unit 1017 | Health & Safety | Blocked/Unusable | L3 | bedroom window blocked by dresser | incomplete |
| | | | | Holes/Missing | | | |
| | | | | Section/Damaged/Falling/Leaning | | 6 foot wrought iron fence has several openings along | |
| Site | | | Fencing and Gates | (Security, Safety) | L3 | street/perimeter | 11/5/2023 |
| | | | | | | | |
| Site | | | Grounds | Overgrown/Penetrating Vegetation | L3 | building gutters growing vegetation | 11/6/2023 |

| | | | | Cracks/Settlement/Heaving/Loose | | T | |
|----------|------------|-----------|-------------------|--|----|--|-------------|
| Site | | | Parking/Drives | Materials/Potholes | L2 | bldgs 705 & 2112 | 11/5/2023 |
| Site | | | Retaining Walls | Damaged/Falling/Leaning | L3 | near 2103, 2105, 2107, 2108 | 11/7/2023 |
| Building | | | Thetaning Trans | 24864, 148, 2548 | | near 2105, 2105, 2107, 2105 | 11,7,1010 |
| Exterior | Bldg 2100 | | Walls | Missing Pieces/Holes/Spalling | L2 | stucco deteroiraed/damaged | 11/6/2026 |
| Building | 2.08 2200 | | | g · · · · · · · · · · · · · · · · · | | Wood Deterioration at balconies, fascia, soffit visible at | 11, 0, 1010 |
| Exterior | Bldg 2101 | | Walls | Missing Pieces/Holes/Spalling | L2 | 1127 & 2127 | 11/4/2023 |
| Building | | | | The state of the s | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 2101 | | Electrical System | Missing Covers | L3 | exposed electric connections | 11/7/2023 |
| -, | | | | Mold/Mildew/Water Stains/Water | | | |
| Unit | Bldg 2101 | unit 1129 | Ceiling | Damage | L3 | bathroom ceiling over shower at a/c | 11/5/2023 |
| | | | | Emergency Fire Exits - | | | |
| | | | | Emergency/Fire Exits | | | |
| Unit | Bldg 2101 | unit 1129 | Health & Safety | Blocked/Unusable | L3 | Bedroom windows blocked by a/c window units | 11/5/2023 |
| Unit | Bldg 2101 | unit 1129 | Health & Safety | Hazards - Other | L3 | 3 smoke detectors -repaired during inspection | 8/29/2023 |
| Unit | Bldg 2101 | unit 1129 | HVAC System | Not Operable | L3 | a/c inoperable | 11/5/2023 |
| Unit | Bldg 2101 | unit 1129 | Kitchen | Countertops - Missing/Damaged | L2 | severely damaged | 11/5/2023 |
| Unit | Bldg 2101 | unit 1129 | Kitchen | Plumbing - Leaking Faucet/Pipes | L3 | at hot water line | 11/5/2023 |
| | J | | | Range/Stove - | | | |
| Unit | Bldg 2101 | unit 1129 | Kitchen | Missing/Damaged/Inoperable | L3 | 2 burners missing | 11/5/2023 |
| Building | | | | Missing/Damaged Components from | | | |
| Exterior | Bldg 2101A | | Roofs | Downspout/Gutter | L2 | down spout damaged & splashblocks missing | 11/5/2023 |
| Building | | | | | | | |
| Exterior | Bldg 2101A | | Walls | Cracks/Gaps | L3 | stucco shows large cracks | 11/4/2023 |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 2101A | | Electrical System | Missing Covers | L3 | exposed electric connections | 11/7/2023 |
| Common | | | | | | laundry room is not available to residents-closed/locked- | |
| Areas | Bldg 2101A | Doors | Laundry Room | Damaged Hardware/Locks | L3 | evidence of Transients | 11/1/2023 |
| Unit | Bldg 2101A | Unit 1010 | Doors | Missing Door | L1 | closet door off hinges/missing | 11/6/2023 |
| Building | | | | | | | |
| Exterior | Bldg 2103 | | Walls | Missing Pieces/Holes/Spalling | L2 | Wood Deterioration at balconies, fascia, soffit | 11/4/2023 |
| | | | | Water Closet/Toilet - | | | |
| Unit | Bldg 2103 | Unit 1119 | Bathroom | Damaged/Clogged/Missing | L3 | toilet missing (on order) | 11/4/2023 |
| Unit | Bldg 2103 | Unit 2120 | Health & Safety | Hazards - Other | L3 | X 2 smoke detectors-repaired during inspection | 8/29/2023 |
| | | | | Range/Stove - | | | |
| Unit | Bldg 2103 | Unit 2122 | Kitchen | Missing/Damaged/Inoperable | L3 | inoperable | 11/7/2023 |
| Building | | | | Missing/Damaged Components from | | | |
| Exterior | Bldg 2104 | | Roofs | Downspout/Gutter | L2 | downspout missing | 11/5/2023 |
| Building | | | | | | | |
| Exterior | Bldg 2104 | | Walls | Cracks/Gaps | L3 | stucco stair support near 2039 | 11/5/2023 |

The Jones - 2023 UPCS Inspection Uncorrected = Yellow. Corrected = White

| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
|----------|-----------|------------|------------------------|-----------------------------------|----|---|-----------|
| Systems | Bldg 2104 | | Electrical System | Missing Breakers/Fuses | L3 | exposed electric connections | 11/7/2023 |
| Common | | | 1 | , | | | , , |
| Areas | Bldg 2104 | Stairs | Halls/Corridors/Stairs | Broken/Damaged/Missing Steps | L3 | stairs to 2042 not supported | 11/4/2023 |
| Common | | | | | | | |
| Areas | Bldg 2104 | Floors | Patio/Porch/Balcony | Rot/Deteriorated Subfloor | L3 | unit 2040: patio concrete is broken and unstable | 11/5/2023 |
| Unit | Bldg 2104 | Unit 1042 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | pop-up assembly inoperable | 11/5/2023 |
| | | | | | | interior breaker box not secured to wall -repaired during | |
| Unit | Bldg 2104 | Unit 1042 | Electrical | Missing Covers | L3 | inspection | 8/29/2023 |
| Unit | Bldg 2104 | Unit 1042 | Health & Safety | Hazards - Other | L3 | incense burned in sheetrock wall | 8/29/2023 |
| | | | | Refrigerator- | | | |
| Unit | Bldg 2104 | Unit 1042 | Kitchen | Missing/Damaged/Inoperable | L1 | fresh food seal/gasket damaged | 11/7/2023 |
| Unit | Bldg 2104 | Unit 2040 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | X2 pop-up assembly inoperable | 11/7/2023 |
| Unit | Bldg 2104 | Unit 2040 | Health & Safety | Hazards - Other | L3 | Smoke detectors-Repaired during Inspection | 8/29/2023 |
| Unit | Bldg 2104 | Unit 2040 | Health & Safety | Infestation - Insects | L3 | roaches | 11/8/2023 |
| Building | | | | Missing/Damaged Components from | | | |
| Exterior | Bldg 2105 | | Roofs | Downspout/Gutter | L2 | missing downspouts & splashblocks | 11/5/2023 |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 2105 | | Electrical System | Missing Breakers/Fuses | L3 | exposed electric connections | 11/7/2023 |
| Building | | | | Broken/Leaking/Clogged Pipes or | | | |
| Systems | Bldg 2105 | | Sanitary System | Drains | L3 | sewage leaked into boiler room | 11/7/2023 |
| Common | | | Closet/Utility/Mechani | | | at boiler room-breaker box panel missing-electric | |
| Areas | Bldg 2105 | Electrical | cal | Missing Covers | L3 | connections exposed-repaired during inspection | 8/29/2023 |
| | | | | Mold/Mildew/Water Stains/Water | | | |
| Unit | Bldg 2105 | Unit 1111 | Ceiling | Damage | L1 | at livingroom ceiling: evidence of leak | 11/7/2023 |
| | | | | Damaged | | | |
| Unit | Bldg 2105 | Unit 1111 | Doors | Frames/Threshold/Lintels/Trim | L3 | gap at main entry door | 11/7/2023 |
| | | | | Deteriorated/Missing Seals (Entry | | | |
| Unit | Bldg 2105 | Unit 1116 | Doors | Only) | L3 | daylight visible when entry door is closed | 11/7/2023 |
| Building | | | | | | Wood Deterioration at balconies, fascia, soffit building | |
| Exterior | Bldg 2107 | | Walls | Missing Pieces/Holes/Spalling | L2 | 2107 | 11/4/2023 |
| Common | | | | | | | |
| Areas | Bldg 2107 | Stairs | Halls/Corridors/Stairs | Broken/Damaged/Missing Steps | L3 | stairway leading to unit 2107 | 11/4/2023 |
| Unit | Bldg 2107 | Unit 1106 | Health & Safety | Hazards - Other | L3 | smoke detector-repaired during inspection | 8/29/2023 |
| Unit | Bldg 2107 | Unit 1107 | Bathroom | Cabinets - Damaged/Missing | L1 | second bathroom cabinet damaged | 11/5/2023 |
| Unit | Bldg 2107 | Unit 1107 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | x2 pop up assembly inoperable | 11/7/2023 |
| | | | | | | second bathroom ceiling NIS: cardboard patch over | |
| Unit | Bldg 2107 | Unit 1107 | Ceiling | Holes/Missing Tiles/Panels | L1 | showerhead | 11/7/2023 |
| | | | | Air Quality - Mold and/or Mildew | | | |
| Unit | Bldg 2107 | Unit 1107 | Health & Safety | Observed | L3 | inside second bathroom cabinet | 11/7/2023 |

| | | | | Emergency Fire Exits - | | | |
|----------|------------|-----------|---------------------------------------|--|----|--|-------------|
| | | | | Emergency/Fire Exits | | second bedroom window will not stay up/open resulting | |
| Unit | Bldg 2107 | Unit 1107 | Health & Safety | Blocked/Unusable | L3 | in blocked egress | 11/7/2023 |
| Unit | Bldg 2107 | Unit 1107 | Health & Safety | Infestation - Insects | L3 | roaches | 11/8/2023 |
| Unit | Bldg 2107 | Unit 1107 | Walls | Damaged | L2 | over second bedroom window | 11/5/2023 |
| O'IIIC | 2106 | Ome 1107 | · · · · · · · · · · · · · · · · · · · | Damagea | | second bedroom window will not stay up/open resulting | 11/3/2023 |
| Unit | Bldg 2107 | Unit 1107 | Windows | Inoperable/Not Lockable | L3 | in blocked egress | 11/7/2023 |
| Building | 2106 | Ome 1107 | · · · · · · · · · · · · · · · · · · · | moperable, real Education | | exterior A/c Disconnects missing interior cover-open, | 11,7,2023 |
| Systems | Bldg 2109 | | Electrical System | Missing Breakers/Fuses | L3 | exposed electric connections | 11/7/2023 |
| Building | 2.08 2200 | | | Missing/Damaged Components from | | CAPACCA CIGATIA COMPOSITORIO | 22,7,2020 |
| Exterior | Bldg 2111 | | Roofs | Downspout/Gutter | L2 | downspout broken/not connected | 11/5/2023 |
| Building | Bldg 2112- | | 110013 | Downspour, dutter | | downspour stokeny not connected | 11, 3, 2023 |
| Exterior | TH | | Foundations | Spalling/Exposed Rebar | L3 | rebar exposed near 1053 | 11/4/2023 |
| Building | Bldg 2112- | | . canaanono | Missing/Damaged Components from | | Possil Copessor Hear 2000 | 11, 1, 1010 |
| Exterior | TH | | Roofs | Downspout/Gutter | L3 | gutter on ground near 1053 & downspout missing | 11/5/2023 |
| Building | Bldg 2112- | | 110013 | Downspour, dutter | | Satter on Broama near 1000 a downspoat missing | 11,3,2023 |
| Exterior | TH | | Roofs | Missing/Damaged Shingles | L1 | drip edge missing-visible near unit 1053 | 11/5/2023 |
| Building | Bldg 2112- | | | and the second s | | | , _, |
| Systems | TH | | Electrical System | Missing Covers | L3 | open junction box | 11/7/2023 |
| 7000 | Bldg 2112- | | | | | - Committee of the comm | , , , |
| Unit | тн | Unit 1052 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | clogged & missing drain line | 11/7/2023 |
| | Bldg 2112- | | | , , , , | | | , , |
| Unit | тн | Unit 1052 | Bathroom | Plumbing - Leaking Faucet/Pipes | L1 | tub drips and will not turn off | 11/7/2023 |
| | Bldg 2112- | | | | | · | |
| Unit | тн | Unit 1052 | Bathroom | Shower/Tub - Damaged/Missing | L2 | Primary tub peeling | 11/8/2023 |
| | Bldg 2112- | | | Deteriorated/Missing Seals (Entry | | | |
| Unit | тн | Unit 1052 | Doors | Only) | L3 | daylight visable when entry door is closed | 11/7/2023 |
| | Bldg 2112- | | | | | | |
| Unit | TH | Unit 1052 | Health & Safety | Hazards - Other | L3 | X4 removed by resident-Repaired during Inspection | 8/29/2023 |
| | Bldg 2112- | | | | | open wires visible over interior stairs (possible removed | |
| Unit | TH | Unit 1053 | Electrical | Missing Covers | L3 | light fixture?) | 11/7/2023 |
| | Bldg 2112- | | | Air Quality - Mold and/or Mildew | | | |
| Unit | TH | Unit 1053 | Health & Safety | Observed | L3 | under downstairs bathroom sink | 11/7/2023 |
| Building | | | | | | | |
| Exterior | Bldg 2113 | | Roofs | Missing/Damaged Shingles | L1 | 10 x 10 square damaged/missing shingles | 11/5/2023 |
| | | | | | | | |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 2115 | | Electrical System | Missing Covers | L3 | exposed electric connections; open junction box | 11/7/2023 |
| | | | | Dishwasher/Garbage Disposal - | | | |
| Unit | Bldg 2115 | Unit 2089 | Kitchen | Inoperable | L2 | dishwasher inoperable | 11/7/2023 |

| | | | | Refrigerator- | | | |
|----------|-------------|-----------|-------------------|---------------------------------------|----|---|-----------|
| Unit | Bldg 2115 | Unit 2089 | Kitchen | Missing/Damaged/Inoperable | L1 | freshfood gasket/door seal damaged | 11/7/2023 |
| Unit | Bldg 2115 | Unit 2089 | Windows | Damaged/Missing Screens | L1 | livingroom window screen missing | 11/7/2023 |
| Building | Bldg 2117- | | | Missing/Damaged Components from | | | |
| Exterior | тн | | Roofs | Downspout/Gutter | L1 | missing splashblocks | 11/5/2023 |
| Building | Bldg 2117- | | | , , | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | тн | | Electrical System | Missing Breakers/Fuses | L3 | exposed electric connections | 11/7/2023 |
| , | Bldg 2117- | | , | · · | | | |
| Unit | тн | Unit 1087 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | pop up assembly inoperable | 11/8/2023 |
| | Bldg 2117- | | | | | | |
| Unit | тн | Unit 1087 | Bathroom | Plumbing - Clogged Drains | L3 | bathroom sink clogged | 11/8/2023 |
| | Bldg 2117- | | | Damaged Surface | | | |
| Unit | тн | Unit 1087 | Doors | (Holes/Paint/Rusting) | L1 | door in kitchen also sparyed with expanding foam | 11/8/2023 |
| | Bldg 2117- | | | , , , , , , , , , , , , , , , , , , , | | , , , , | |
| Unit | тн | Unit 1087 | Health & Safety | Hazards - Other | L3 | smoke detector hanging | 11/8/2023 |
| | Bldg 2117- | | | | | | |
| Unit | тн | Unit 1087 | Kitchen | Cabinets - Missing/Damaged | L2 | base cabinets are sprayed with expanding foam | 11/8/2023 |
| | Bldg 2117- | | | 5. 5 | | . , | |
| Unit | тн | Unit 1087 | Kitchen | Countertops - Missing/Damaged | L2 | broken/misaligned near kitchen sink | 11/8/2023 |
| | Bldg 2117- | | | Dishwasher/Garbage Disposal - | | Dishwasher missing, NIS plywood covers space; & | |
| Unit | тн | Unit 1087 | Kitchen | Inoperable | L2 | disposal inoperable | 11/8/2023 |
| | Bldg 2117- | | | | | | |
| Unit | тн | Unit 1087 | Kitchen | Plumbing - Leaking Faucet/Pipes | L3 | leak at washer connection | 11/8/2023 |
| Building | Bldg 2119- | | | Missing/Damaged/Expired | | | |
| Systems | тн | | Fire Protection | Extinguishers | L3 | Boiler room #2 fire extinguisher expired | 11/4/2023 |
| Building | | | | Missing/Damaged Components from | | | |
| Exterior | Bldg 700-TH | | Roofs | Downspout/Gutter | L2 | missing downspout | 11/4/2023 |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 700-TH | | Electrical System | Missing Breakers/Fuses | L3 | exposed electric connections | 11/7/2023 |
| | | | | | | | |
| Unit | Bldg 700-TH | Unit 1079 | Bathroom | Plumbing - Leaking Faucet/Pipes | L3 | oth tubs drip constantly; can not be turned off | 11/5/2023 |
| | | | | Water Closet/Toilet - | | | |
| Unit | Bldg 700-TH | Unit 1079 | Bathroom | Damaged/Clogged/Missing | L3 | downstairs toilet inoperable | 11/5/2023 |
| | | | | | | interior breaker box not secure to wall-repaired during | |
| Unit | Bldg 700-TH | Unit 1079 | Electrical | Missing Breakers/Fuses | L3 | inspection | 8/29/2023 |
| | | | | | | | |
| Unit | Bldg 700-TH | Unit 1079 | Health & Safety | Hazards - Other | L3 | smoke detector primary bedroom missing | 11/7/2023 |
| | | | | Dishwasher/Garbage Disposal - | | | |
| Unit | Bldg 700-TH | Unit 1079 | Kitchen | Inoperable | L2 | dishwasher does not close/lock and leaks when used | 11/7/2023 |
| | | | | | | dishwasher does not close and lock and therefore leaks | |
| Unit | Bldg 700-TH | Unit 1079 | Kitchen | Plumbing - Leaking Faucet/Pipes | L3 | onto floor when in use | 11/7/2023 |

The Jones - 2023 UPCS Inspection Uncorrected = Yellow. Corrected = White

| Building | | | | | | | |
|----------|-------------|-----------|---------------------|---------------------------------|----|---|-----------|
| Exterior | Bldg 701 | | Walls | Missing Pieces/Holes/Spalling | L2 | wood balconies severly deteriorated | 11/4/2023 |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 701 | | Electrical System | Missing Covers | L3 | exposed electric connections | 11/7/2023 |
| | | | | | | | |
| Common | | | | | | 2002 patio-no structural support-severe Deterioration- | |
| Areas | Bldg 701 | Floors | Patio/Porch/Balcony | Rot/Deteriorated Subfloor | L3 | concrete cracked and moves when stepped on | 11/5/2023 |
| Unit | Bldg 701 | Unit 2002 | Porch/Balcony | Baluster/Side Railings Damaged | L3 | loose | 11/5/2023 |
| | | | | | | kitchen sink leak causing damage to cabinets (under | |
| Unit | Bldg 701 | Unit 2008 | Kitchen | Plumbing - Leaking Faucet/Pipes | L3 | sink) | 11/7/2023 |
| | | | | Range/Stove - | | | |
| Unit | Bldg 701 | Unit 2008 | Kitchen | Missing/Damaged/Inoperable | L2 | missing burner | 1/4/2023 |
| Building | | | | | | | |
| Exterior | Bldg 705 | | Health & Safety | Hazards - Tripping | L3 | sidewalk behind building | 11/4/2023 |
| Building | | | | Missing/Damaged Components from | | | |
| Exterior | Bldg 705 | | Roofs | Downspout/Gutter | L2 | downspouts damaged & splashblocks missing | 11/4/2023 |
| Building | | | | | | stucco displays holes near wooden patio fence & gaps at | |
| Exterior | Bldg 705 | | Walls | Missing Pieces/Holes/Spalling | L2 | corners | 11/4/2023 |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 705 | | Electrical System | Missing Covers | L3 | exposed electric connections | 11/7/2023 |
| | | | | | | X2 smoke detectors inoperable-Repaired during | |
| Unit | Bldg 705 | Unit 1017 | Health & Safety | Hazards - Other | L3 | Inspection | 8/29/2023 |
| Building | | | | | | | |
| Exterior | Bldg 707-TH | | Walls | Missing Pieces/Holes/Spalling | L2 | stucco displays holes near wooden patio fence | 11/4/2023 |
| Building | | | | | | exterior A/c Disconnects missing interior cover-open, | |
| Systems | Bldg 707-TH | | Electrical System | Missing Breakers/Fuses | L3 | exposed electric connections | 11/7/2023 |
| Unit | Bldg 709 | Unit 2031 | Bathroom | Lavatory Sink - Damaged/Missing | L1 | X2 pop up assembly inoperable | 11/5/2023 |
| Unit | Bldg 709 | Unit 2031 | Bathroom | Shower/Tub - Damaged/Missing | L2 | tub overflow missing | 11/5/2023 |
| | | | | Soft Floor Covering | | | |
| Unit | Bldg 709 | Unit 2031 | Floors | Missing/Damaged | L2 | damage/stain | 11/5/2023 |
| | | | | Emergency Fire Exits - | | | |
| | | | | Emergency/Fire Exits | | | |
| Unit | Bldg 709 | Unit 2031 | Health & Safety | Blocked/Unusable | L3 | X2 window a/c units block both bedroom windows | 11/5/2023 |
| | | | | Dishwasher/Garbage Disposal - | | | |
| Unit | Bldg 709 | Unit 2031 | Kitchen | Inoperable | L2 | disposal inoperable | 11/5/2023 |
| | | | | | | balluster at stairway leading to main entry door-is | |
| Unit | Bldg 709 | Unit 2031 | Porch/Balcony | Baluster/Side Railings Damaged | L3 | loose/concrete at entry is broken and unstable | 11/4/2023 |