

Attachment 1: Inspection Report - All Corrected

Bldg	Apt	Location	Item	Result	Notes	Sev.	Date Corrected	Corrected By (Name or Contractor)
1	101	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)		Severe		
1	101	Kitchen	Fire Extinguisher	Fire extinguisher pressure gauge reads over- or under-charged		LT		
1	105	Bathroom	Conductors, Outlets, Switches	Exposed electrical conductor		LT		
1	105	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)		Severe		
1	201	Bathroom	Sink	Sink stopper missing or inoperable		Low		
1	201	Kitchen	Fire Extinguisher	Fire extinguisher pressure gauge reads over- or under-charged		LT		
1	203	Bathroom	Sink	Sink stopper missing or inoperable		Low		
1	203	Kitchen	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)		Severe		
2	109	Kitchen	Fire Extinguisher	Fire extinguisher pressure gauge reads over- or under-charged		LT		
2	212	Kitchen	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)	Does not trip when button pushed. Outlet to right of sink.	Severe		
3	213	Bathroom	Sink	Sink stopper missing or inoperable		Low		
3	214	Bathroom	Sink	Sink stopper missing or inoperable		Low		
3	218	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)	Does not trip when button pushed. Outlet to right of sink.	Severe		
3	223	Kitchen	Fire Extinguisher	Fire extinguisher pressure gauge reads over- or under-charged		LT		
4	127	Bathroom	Sink	Sink stopper missing or inoperable		Low		
4	128	Bathroom	Plumbing & Water Leaks	Plumbing Leaks	Tub dripping 	Mod		
4	128	Bathroom	Sink	Sink stopper missing or inoperable		Low		
4	128	Kitchen	Refrigerator	Refrigerator drawers or shelving is damaged	Bottom drawer missing	Mod		
4	129	Bathroom	Sink	Sink stopper missing or inoperable		Low		
4	129	Bathroom	Sink	Sink is improperly installed, leaning, or pulling away from wall	Right side, pulling away from the wall	Mod		
4	129	Hallways & Corridors	Smoke Alarms	Smoke alarm does not produce an audio or visual alarm when tested	Rdi	LT		
5	136	Bathroom	Sink	Sink stopper missing or inoperable		Low		
5	139	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)	Does not trip when button pushed. Outlet to left of sink.	Severe		
5	140	Bathroom	Sink	Sink stopper missing or inoperable		Low		

5	141	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)		Severe		
5	141	Bathroom	Sharp Edges	Any item or component has a sharp edge that can puncture or cut		Severe		
5	236	Bathroom	Sink	Sink stopper missing or inoperable		Low		
5	236	Kitchen	Infestation	Evidence of cockroaches (Live, Dead, or Other Evidence)		Mod		
5	238	Bathroom	Sink	Sink stopper missing or inoperable		Low		
5	240	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)	Does not trip when button pushed. Outlet to right of sink.	Severe		
5		Side of Building	Sharp Edges	Any item or component has a sharp edge that can puncture or cut	Glass on the ground left of the unit 141	Severe		
5		Walkway/Steps	Tripping Hazard	Tripping hazard - 3/4in. vertical difference	Sidewalk in front of building five unit 145	Mod		
6	147	Bathroom	GFCI/AFCI	GFCI outlet or GFCI breaker reset button does not test (No visible damage)	Does not trip when button pushed. Outlet to left of sink.	Severe		
6	147	Kitchen	Refrigerator	Refrigerator door seal is damaged		Mod		
7	156	Kitchen	Fire Extinguisher	Fire extinguisher pressure gauge reads over- or under-charged		LT		